



Machines under long shutdown require additional care upon startup. Here are some tips to ensure your machines and your business picks up right from where it left off.

GEARBOXES



Start the gearbox under no load condition



Check the oil level and top up if required



Inspect the heat exchanger, descale if ΔT is low



Remove dust and dirt from the GB to ensure proper cooling during operation